



Test Report

Sample Name : LED Flood Light

Sample Model : AOK-1200WfSC-NV-aa-bb-ccdd-zz-P

Inspection : Commission test

Manufacturer : AOK Industrial Company Limited

Client : AOK Industrial Company Limited

Testing L








Guangzhou LCS Compliance Testing Laboratory Ltd.







Page 2 of 11 Report No.: LCSC08213012K

Test Report

Client : AOK Industrial Company Limited

: 1/F of 1#Building, East Block of 3/F of Building 1,And 2/F of Building 4, ST George's

Address Science and Technology Industrial Park, Northside of Xinyu Road, Xiangshan

Community, xinqiao street Baoan District,518000 Shenzhen, Guangdong, CHINA

Manufacturer : AOK Industrial Company Limited

: 1/F of 1#Building, East Block of 3/F of Building 1,And 2/F of Building 4, ST George's

Address Science and Technology Industrial Park, Northside of Xinyu Road, Xiangshan

Community, xinqiao street Baoan District,518000 Shenzhen, Guangdong, CHINA

The following sample(s) and sample information was/were submitted and identified by/on the behalf of the client:

Sample Name : LED Flood Light

Sample Model : AOK-1200WfSC-NV-aa-bb-ccdd-zz-P

Sample Quantity : 1PC

Sample tested Status : Normal

Sample received Date : Oct.25, 2023

Sample tested Date : Oct.30, 2023

Trade mark :

Test result information:

Test item : 3G Vibration Test

Test standard : ANSI C136.31-2018

Test result : PASS

Heal Chen

Sound chen

home

Edited by

Heal Chen

Checked by

Sound Chen

Approved by

Kizard Zhang

Oct.31, 2023

Oct.31, 2023

Oct.31, 2023





Test Report

Revise Record

Report version	Issued date	Revision times	Revised content	Valid version
LCSC08213012K	Oct.31, 2023	1	Original Report	Valid
- 古讯检测的	(A)	古语检测报告	0 - 1	讯检测度给
LCS Testin		LCS Testino	100	051esti
14 测股份		份	一位测股份	
LCS Testing Lan	LCS Testing	1	LCS Testing Lab	LCS Test
	us.	- 112		TO THE PE
工河域 Ti开位测量	4 \/ / /	工资 Till Till Re 12	o NG	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		The local section of the local	152	



Guangzhou LCS Compliance Testing Laboratory Ltd.

Add: No 44-1, Qianfeng North Road, Shiqi, Panyu District, Guangzhou, Guangdong, China Tel: +(86) 020-39166689 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com Scan code to check authenticity





Test Report

Test Item: 3G Vibration Test

1) Environment conditions:

Temperature: 23.5 °C Humidity: 56%RH

2) Tested Sample:

Sample No.	Sample Name	Sample Model	Sample Quantity	Sample Description
C08213012-001	LED Flood Light	AOK-1200WfSC-NV- aa-bb-ccdd-zz-P	1PC	Normal

Remark: Customer statement: "aa" can be any letters to denote manufacturer of LED;

"bb" denotes dimming control; 00=No sensor provided, PH=Plug-In photocontrol or NEMA Short-circuit cap provided, DV=dimming function

"cc" can be 27, 30, 40, 50, 57 or 65 to denote colour temperature of LEDs, e.g. 27=2700K, 30=3000K, 40=4000K, 50=5000K, 57=5700K, 65=6500K;

"dd" can be 70, 80 or 90 to denote colour rendering index of LEDs, e.g. 70: CRI: 70, 80: CRI: 80, 90: CRI: 90:

"zz" can be any letter or number to denote beam angles.

3) Reference Basis: ANSI C136.31-2018

4) Test Condition:

- 1. Secure to the console and secure:
- 2. Swept Vibration:
 - a) Frequency(Hz): 2-30;
 - b) Acceleration(G): 0.2;
 - c) Swept rate(Oct/min): 1;
 - d) Test axial: X, Y, Z.
- 3. Fixed Vibration:
 - a) Frequency(Hz): X-10.09Hz, Y-10.99Hz, Z-30.00Hz;
 - b) Acceleration(G): 3;
 - c) Test cycle(Times): 100000;
- 4. Sample test condition: Non-Operation.
- 5. Judgement requirements:After the test, the sample has no visual damage, no parts are loose in inside.The sample lit up normally.







Page 5 of 11

Test Report

5) Test Equipment:

Sequence	Equipment Name	Equipment No.	Valid Date to
1	Vibration tester	GLCS-S-177	Aug.13, 2024

6) Test Results:

Sample No.	Test Result	Judge
C08213012-001	After the test, the sample has no visual damage, no parts are loose in inside. The sample lit up normally.	PASS















Report No.: LCSC08213012K








Test Report

Sample Photo before the Test:



Appearance inspection



Report No.: LCSC08213012K

Light up inspection

Sample Photo during the Test:



X axis



Y axis




Z axis



Z axis








Page 7 of 11 Report No.: LCSC08213012K

Test Report

Sample Photo after the Test:



Appearance Inspection-Front



Appearance Inspection-Back



Inside inspection



Light up inspection














Test Report










Test Report












Test Report









Test Report

NOTES:

- 1. The report be without test report seal is considered as INVALID.
- 2. The content of reports cannot be copied without written consent of lab.
- 3. The report will be invalid without signature of testing person, review person and approved person.
- 4. Report will be invalid if altered.
- 5. If there is any objection to the test report, it should be submitted to the lab within 15 days. Otherwise, objection invalid.
- 6. Lab is responsible to the testing samples only.
- 7. The report is only for use of internal by customer or scientific research.
- 8. The applicant and manufacturer's information, product name, model, trademark and other information in this report are provided by the applicant, and the laboratory is not responsible for verifying their authenticity.

Lab Address: No 44-1, Qianfeng North Road, Shiqi, Panyu District, Guangzhou, Guangdong, China

Tel: 86-020-39166689 P.C: 511450







