

Report No.:SZA EK190703010-01

Test Report

Client Name : AOK Industrial Company Limited

Address : East Seat, Three Floor Building One, Shengzuozhi Science and Technology Industrial Park, Xinyu Road North Side, Shajing Street, Baoan District, 518000 Shenzhen, Guangdong, PEOPLE'S REPUBLIC OF CHINA

Product Name : LED Street Light

Date : 2019.07.04

Shenzhen Anbotek Compliance Laboratory Limited



Report No.:SZAEK190703010-01

Marking

1. The test report is invalid without the official stamp of Shenzhen Anbotek Compliance Laboratory Limited.
2. Nobody is allowed to photocopy or partly photocopy this test report without written permission of Shenzhen Anbotek Compliance Laboratory Limited.
3. The test report is invalid without the signatures of testing engineer, reviewer and approver.
4. The test report is invalid if altered.
5. Objections to the test report must be submitted to Shenzhen Anbotek Compliance Laboratory Limited within 15 days.
6. The test report is valid for the tested samples only.
7. As for test verdict, “—”means “no need for judgment” “N/A” means “not applicable”.



Report No.:SZA EK190703010-01

TEST REPORT

Client Name : AOK Industrial Company Limited
Address : East Seat, Three Floor Building One, Shengzuozhi Science and Technology Industrial Park, Xinyu Road North Side, Shajing Street, Baoan District, 518000 Shenzhen, Guangdong, PEOPLE'S REPUBLIC OF CHINA

Report on the submitted sample(s) said to be:

Sample Name : LED Street Light
Model : Please see the page 5.

Trademark : 

Description : /

Sample(s) received quantity : 1

Sample(s) Testing quantity : 1

Manufacturer : AOK Industrial Company Limited

Factory : AOK Industrial Company Limited

Other information : /

Sample(s) received Date : 2019.07.03

Testing period : 2019.07.03

Report Date : 2019.07.04

Report No.:SZA EK190703010-01

Test Conclusion :

Item No.	Test Item	Test Standard	Evaluation
1	IK09	IEC 62262-2002	PASS



Prepared by:

Jarvan Zheng

Name: Jarvan Zheng
Title: Test Engineer

Checked by:

Jimmy Zhou

Name: Jimmy Zhou
Title: Lab Manager

Approved by:

Mike Jiang



Name: Mike Jiang
Title: Authorized signatory

Report No.:SZA EK190703010-01


The model information for the sample is as follows:

Ordinal No.	Product Name	Model	Note
1	LED Street Light	AOK-120WiP-NV-L3-00-XX70-T5-P-I	Test sample
2		AOK-75WiP-NV-L3-00-XX70-T5-P-I	/
3		AOK-60WiP-NV-L3-00-XX70-T5-P-I	/
4		AOK-50WiP-NV-L3-00-XX70-T5-P-I	/
5		AOK-40WiP-NV-L3-00-XX70-T5-P-I	/
6		AOK-30WiP-NV-L3-00-XX70-T5-P-I	/
7		AOK-25WiP-NV-L3-00-XX70-T5-P-I	/
8		AOK-20WiP-NV-L3-00-XX70-T5-P-I	/


Report No.:SZAEK190703010-01

1. IK09				
Test Standard	IEC 62262-2002			
Test Condition	<p>The test remark and the matters needing attention:</p> <p>--- the sample is Installed on the rigid support surface, Begin the impact test from a height of 200 mm using the pendulum 5 kg, The energy of impact test specimens for 10J;</p> <p>--- The impact of 5 points evenly distributed in the each exposed surface of the sample;</p> <p>--- There shall be no more than three collisions applied near the same position of the enclosure;</p> <p>--- Check the sample after the test.</p>			
Test Equipment	Equipment Name	Equipment No.	Equipment model	Equipment Cal validity period
	IK impact tester	SE-1459	GRPH-2	2019.12.19
Test Result	Sample No.	Test requirements	Test Result	Evaluation
	SZAEK190703010-S1	The sample housing is allowed to be slightly cracked, dented and not to be seriously damaged.	The sample housing is normal after test.The sample housing is not cracked,dented and damaged.	PASS
Photos				
	Before Test		Before Test	

Report No.:SZA EK190703010-01



Before Test



Before Test

Photos



Test set-up



Test set-up









Test set-up



Test set-up

Report No.:SZA EK190703010-01

Photos		
	After Test	After Test
		
	After Test	After Test
		
	After Test	After Test

End of Report